Peter Chipkin

Subject: FW: 450 default
Attachments: Serial Comm Module Installation (G).pdf

Take a look at the table on pg 8 that covers all of them for the 350.
330148-001, 847490-303
329362-001, 847490-301
330586-001, 847490-311
330586-017, 847490-317
These are the only cards I would even remotely suggest connecting for communication to a serial device

Moving onto the 450 I think there is only 1 card still available
The dual port it has 2 db9s at the bottom
332868-001

Comm Bay

Module Bay

Power connector
cover plate
(shown removed)

WARNING - HIGH
VOLTAGE UNDER
THIS COVER

AC power
input connector
120/240 Vac,
50/60 Hz,
2A maximum

1 2 3 4 5

NO
C

Overfill alarm
relay connector
120/240 Vac,
2A maximum

Module clamp
securing screw

1 2 3 4

Dual-port
Comm Device

Front of console

Port 1

Port 2

1 2 3 4 5

Comm Device slots

Bottom of console

MODULE	PER S
USM Module	
I/O Module	1
MDIM	
LVDIM	

They say there is a 1 port 332866-001 but I've never even seen a photo of one.
There is one more it looks identical to the dual port and has one rs232 port and a non functioning rs485 port.